

0/10/2021



18aWA203-7

# MEG II実験背景事象抑制のための DLC-RPC の長期安定性の評価

# 鈴木 大夢(神戸大理)

#### 神戸大理,東大素セ<sup>A</sup>,東大理<sup>B</sup>

大谷 航<sup>A</sup>, 大矢 淳史<sup>A</sup>,越智 敦彦,高橋 真斗

潘 晟<sup>A</sup> 山本 健介<sup>B</sup> 李 維遠<sup>B</sup>, 他MEG IIコラボレーション

2024年9月18日

日本物理学会第79回年次大会

# Table of contents

18aWA203-7

1

#### Introduction

- DLC-RPC in the MEG II experiment
- Discharges in the past tests
- What induces discharges
- Electrode type change
- Long-term operation
  - Setup

01202/

- Procedure
- Result of a test with  $\beta$ -rays ( $\mathcal{O}(100)$ kHz)
- Result of a test with  $\beta$ -rays ( $\mathcal{O}(10)$ kHz)
- Pulse-height spectra at 2600 V and 2625 V
- Comparison with the high-rate radiation
- Summary & Prospects

本物理学会第79回年次大会

# DLC-RPC in the MEG II experiment

DLC-RPC:Resistive Plate Chamber with Diamond-Like Carbon electrodes

Requirements for the DLC-RPC \_\_\_\_

- 1. Material budget: < 0.1 %  $X_0$
- 2. Rate capability: 3 MHz/cm<sup>2</sup>
- Radiation hardness: ∼100 C/cm<sup>2</sup> in 20 weeks operation
- 4. Detection efficiency: > 90 % for MIP
- 5. Timing resolution: < 1 ns
- 6. Detector size: 16 cm Φ

DLC-RPC  $\mu^+$  beam  $e^+$  (RMD)  $\rightarrow$  High intensity (7 × 10<sup>7</sup> /s)  $\rightarrow$  Low momentum (28 MeV/c)

#### An electrode for a small prototype

18aWA203-7



日本物理学会第79回年次大

### Discharges in the past tests

9/18/2024





18aWA203-7

P

Irradiation tests with muons or X-rays have done to evaluate the rate capability and aging.

Discharges on the DLC-RPC have prevented the operation.

]本物理学会第79回年次大会

# What induces discharges

Conductive strip /

 $(50 \,\mu m \, width)$ 

Protection cover

 $(200 \ \mu m \ width)$ 

18aWA203-7

P

Discharge

### Where discharges happen

Anode



(a) Top view of the spacer

9/18/2024

(b) Oblique view of the spacer

Pillars

### **Possibilities**

Protection covers

Spacing pillars  $(\Phi 400 \ \mu m, 2.5 \ mm pitch)$ 

- Accumulated damage
  - Discharges can occur when a certain amount of damage is stored.
- High-intensity radiation
  - Such radiation induces large gas amplification potentially leading to fatal damage.
- Unstable structure
  - Positions where discharges happen easily

学会第79回

Cathode

#### Flatness issues

# Electrode type change





本物理学会第79回年次大会

9/18/2024

Gas:C<sub>2</sub>H<sub>2</sub>F<sub>4</sub>(R134a)/SF<sub>6</sub>/i-C<sub>4</sub>H<sub>10</sub>= (94/1/5)%

18aWA203-7 🕠

# <u>Procedure</u>

0/18/2024



Minimum Operating Voltage: 2600 V Based on the previous discussion regarding its sufficient detection efficiency and the gain.

18aWA203-7

P

Two  $\beta$ -ray rates

- ♦ High rate: O(100)kHz
- ► Low rate: O(10)kHz

## Result of a test with $\beta$ -rays ( $\mathcal{O}(100)$ kHz)



The operation lasted for 8 hours.

0/18/2024

The detector could operate for no more than 4 - 8 hours under this condition.

18aWA203-7

Spikes started occurring and large ones terminated the operation.

### Result of a test with $\beta$ -rays ( $\mathcal{O}(10)$ kHz)



18aWA203-7

P

- Frequent spikes at 2625 V $\rightarrow$ Less stable than 2600 V
- Current fluctuation was due to variations of the atmospheric conditions and imprecise positioning of the RI.

日本物理学会第79回年次大会

9/18/2024

### Pulse-height spectra at 2600 V and 2625 V



DAQ at the operation voltage was done six times during the long-term operation.
 No change of the pulse-height spectra during each periods

 —Consistent performance at each voltage in terms of the detection

18aWA203-7

P

本物理学会第79回年次大会

9/18/2024

# Comparison with the high-rate radiation



The lower intensity is, the longer the operation gets.

0/10/2024

High-intensity radiation causes large discharges which terminate the operation earlier.

Not tolerant to high-intensity ones and the resistivity is too low?

Higher resistivity electrodes and lowering operating voltage are needed.

18aWA203-7

P

# Summary & Prospects

# <u>Summary</u>

◆DLC-RPC requires 20 weeks operation in the MEG II experiment

• Discharges stop the operation and cause damages to the detector.

#### Long-term operation

- Tests with new electrodes was done to investigate the discharges.
- The operation is hindered easily with the high-rate radiation.
- Obtained pulse-height spectra showed that the long-term operation did not influence on the performance at 2600 V and 2625 V

18aWA203-7

• However, discharges ended up occurring at a certain point in the period even with the low-rate one.

# Summary & Prospects

## Prospects

0/10/202/

Investigating the weak point of the structure for a high-intensity radiation

- Around the pillars
- Conductive strips
- Resistivity
- Survey for the proper operation for the long-term stability
  - Operating voltage
- Fabricating the next module to test the performance in a high-intensity muon beam
  - Designing
  - Operation
    - Satisfy 90 % detection efficiency for MIP, the rate capability of 3 MHz/cm<sup>2</sup>, and the radiation hardness of 100 C in 20 weeks operation.

18aWA203-7

# Backup

18aWA203-7

15

9/18/2024 / 日本物理学会第79回年次大会

## Procedure

- Condition the detector
  - Raising the voltage gradually
  - Irradiation at lower voltages
- Place a Sr90 2 cm from the detector
  - Accumulate integrated charge as much as in the past tests
  - Examine the influence by lowering the intensity
- Begin long-term irradiation at the operation voltage
- Put Sr90 is put 0 cm from the detector to do DAQ in 10 minutes



**DLC-RPC** active region

18aWA203-7

**Results** After the conditioning, the DLC-RPC was being irradiated.

Some spikes happened during the second half of the irradiation period.

18aWA203-7

1



Fluctuation of current
 The temperature change
 Imprecise positioning of the RI

0/10/202/

# <u>Procedure</u>

0/10/202/

Pulse height spectra in the previous talk



Minimum Operating Voltage: 2600 V Based on the previous discussion regarding its sufficient detection efficiency and the gain.

18aWA203-7

P

18

- $\beta$ -ray is irradiated during the operation.
- Comparison
  - High rate
  - Low rate



9/18/2024



18aWA203-7

19

|本物理学会第79回年次大会

# What induces discharges

# Main factors

- 1. Pillars
  - Distort the electric field or enha amplification
- 2. Conductive strip cover
  - Insufficient quenching
- 3. Flatness issues
  - Setup or the bad structure of the electrodes→Non-flatness
  - Non-uniform electric field
- 4. Contamination

0/18/202/

Sparks caused by dusts between the gap

学会第79回年次大会



18aWA203-7





本物理学会第79回年次大会

18aWA203-7

22

#### Pulse-height distribution

Comparison between the start and 24 hours later





18aWA203-7

24

Normarised entries

9/18/2024

日本物理学会第79回年次大会

### Long-term irradiation



18aWA203-7

P

25

日本物理学会第79回年次大会

9/18/2024



本物理学会第79回年次大会

9/18/2024



18aWA203-7

26

#### Discharge marks Anode

9/18/2024



Cathode

18aWA203-7 🚺

These marks were not removed completely.

学会第79回年次大会

## The structure of the DLC-RPC

### DLC-RPC and the upstream RDC



18aWA203-7 🕥

28

| 日本物理学会第79回年次大会

9/18/2024

# What induces discharges

- 1. Flatness issues
- 2. Dusts
- 3. Pillars

0/18/202/

4. Inadequate conditioning and baking with an RI5. Resist cover



(Ф 400 µm, 2.5 mm pitch) 高橋真斗, 日本物理2024 年春季大会, 2024 年3月21 日

Non-flatness of electrodes



29

18aWA203-7

### Discharges in the past tests



(a) Top view of the spacer

(b) Oblique view of the spacer

Fig. 10. Discharge via a pillar.

Masato Takahashi., et al.

0/18/2024

Nucl. Instrum.Methods Phys.Res.Sect A, 1066 (2024), Article 169509



#### 高橋真斗, 日本物理2024 年春季大会, 2024 年3 月21 日

30

18aWA203-7

Discharges on the DLC-RPC have hindered the operation.
Via a pillar
Along an Insulation cover

日本物理学会第79回年次大会

#### Procedure

- Conditioning at 1500 V w/o an RI for 1 hour
- Raising the voltage from 1500 V~2000 V by increments of 100 V in 5 min
- Irradiated at 2000 V w/o a collimator for 5 min (2 cm above for 2.5 min, 0 cm for 2.5 min)
- Same as above at 2100 V (2 cm above for 5 min, 0 cm for 5 min )
- Same at 2200 V (2 cm above for 7 min, 0 cm for 7 min )



Irradiation 2 cm above

0/10/202/

To bake dusts in the wider area of the electrode.



Irradiation 0 cm above

18aWA203-7

### Procedure

- 2300 V
  - 2 hours irradiation in total
  - Position Scanning
  - DAQ
- 2400 V:Same procedure as 2300
   V
- 2450 V:Same procedure
- 2500 V:Same, but irradiation time is shortened to 1 hour in total
- 2600 V:Same and long-term irradiation is started
- DAQ several times and once 24 hours later

### **Position scanning**



18aWA203-7

### Old pillar



### New pillar in 2023



勿理学会第79回年次大会

#### New pillar in 2024



33

Pyralux Dupont

9/18/2024

Dynamask Eternal

18aWA203-7 🗘

COBRA

superconducting magnet

Liquid xenon photon detector (LXe)

# MEG II experiment

- > Searches for the  $\mu \rightarrow e\gamma$  decay
- Charged lepton flavor violation process (cLFV)
- Discovery would be an evidence for new physics
- Aims for a sensitivity of  $6 \times 10^{-14}$ (MEG:  $5.3 \times 10^{-13}$ )



# Radiative decay counter (RDC)

- > Detecting low momentum  $e^+$  and tagging BG- $\gamma$  from the RMD
- Reducing the background events





### Requirements for the upstream RDC

- 1. Material budget: < 0.1 %  $X_0$
- 2. Rate capability: 3 MHz/cm<sup>2</sup>
- 3. Radiation hardness: 20 weeks operation
- 4. Detection efficiency: > 90 % for MIP
- 5. Timing resolution: < 1 ns
- 6. Detector size: 20 cm  $\Phi$

DLC-RPC: Resistive Plate Chamber with electrodes based on Diamond-Like Carbon

18aW

# DLC-RPC

0/18/2024

Diamond-Like Carbon (DLC)

- High resistivity and thin film
- Adjustable resistivity



PCS Instruments, The Science Behind Diamond like Coatings (DLC), <u>https://pcs-instruments.com/articles/the-science-behind-diamond-like-coatings-dlcs/</u>, December 3, 2021

Resistive Plate Chamber (RPC)

- Gaseous detector consisting of parallel plate electrodes
- Fast timing efficiency
  - Higher detection efficiency by stacking layers (Detection efficiency of n-layers:  $\epsilon_n = 1 - (1 - \epsilon_1)^n$ )





38

18aWA203-7

P

Pillars to sustain a gap between electrodes

0/18/202/

More than 40 % detection efficiency with a single layer is required. →90 % efficiency with 4 layers

日本物理学会第79回年次大

# First prototype



# First prototype

#### Issues

0/18/202/

### 1. Distortion of an electric field

- Inhomogeneous pillars that made the non-uniform gap
- Fixing method that causes the thin-film electrode to be  $\bullet$ distorted

### 2.Insufficient quench





#### Distorted spacing pillar



Non-flatness of electrodes



P

18aWA203-7

(Φ 400 um, 2.5 mm pitch

### Production of new electrodes



18aWA203-7

0/10/202/

### Performances with new electrodes

## Result

0/10/202/



18aWA203-7

P

42

- ◆ 57 % detection efficiency was achieved at 2.65 kV.
- The operation will be performed at 2.63 kV for its stability.